## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.


As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

optical coating 2	
glass substrate 1	

FIG. 1A

·	carbon protective layer 3	
	optical coating 2	
	glass substrate 1	

FIG. 1B



carbon protective coating 3
scratch propagation blocker layer 4
Si₃N₄ layer 2a
optical coating 2
glass substrate 1

FIG. 2




FIG. 3

optical coating 2	
glass substrate 1	

FIG. 4A

metal layer 5	
optical coating 2	
glass substrate 1	

FIG. 4B

scratch propagation blocker layer 4	
	optical coating 2
	glass substrate 1

FIG. 4C




FIG. 5




FIG. 6